Wiser 2 / C-Bus Home Controller Release Notes

C-BUS

Table of Contents

Wiser 2 / SpaceLogic C-Bus Home Controller 1
Released 1
Versions 1
What's New 1
Known Issues 1

Wiser 2 / SpaceLogic C-Bus Home Controller

Released

June 2022

Versions

1.32.4 (Wiser 2)
2.00.11 (SpaceLogic C-Bus Home Controller)

What's New

- Replacement of the Adobe Flash project visualization with a HTML project visualization
- Security fixes
- New firmware to support the above

Please download the latest version of PICED (version 4.14.0) to update the firmware on your Wiser 2 / C-Bus Home Controller.

For more details on PICED, please review the PICED 4.x Release Notes on www.se.com or https://ecoxpert.se.com/spacelogic-c-bus/software-and-firmware#tab/documents.

⚠ *Please ensure you have the latest iOS app (version 3.3 build 27 or greater) and Android app (version 4.0 or greater) before doing the firmware update, as the older version of these apps will not be compatible with the new firmware*.

⚠ *It is strongly recommended that you refresh your project by transferring it from the Wiser 2 before upgrading the firmware*.

⚠ *Once you have upgraded the firmware on your Wiser 2 to this new version or above, you will not be able to downgrade it to a version less than this one*.

⚠ *The full firmware update process when initiated from PICED can take up to 15 minutes. Following the update, the Wiser 2 will reboot and this can take up to two minutes*.

Known Issues

The following issues are known:

- The HVAC widget does not work in the web client. As a work around, the HVAC widget works in the mobile client.
- Ripple support is not working in the mobile client.

There will be a new release in the near future that addresses these issues.